

505 East Huntland Drive Suite 250 Austin, TX 78752

512.329.6080 PHONE 512.329.8750 FAX

www.TRCsolutions.com

May 21, 2012 TRC Solutions Project No. 192355

Mr. Gary Moore U.S. EPA Region 6 1445 Ross Avenue, Suite 1200 Dallas, TX 75202-2733

Re: Weekly Progress Report
Falcon Refinery Superfund Site
Ingleside, San Patricio County, Texas

TXD 086 278 058

Dear Mr. Moore:

On behalf of Lazarus Texas Refinery I, LLC, (Lazarus), TRC Solutions (TRC) submits this Weekly Progress Report on the Removal Action Activities at the Falcon Refinery Federal Superfund Site to the United States Environmental Protection Agency for your review.

If you have any questions, comments, or concerns, please do not hesitate to contact me at (361) 522-1935.

Sincerely, TRC

Alonzo G. Arredondo Senior Geologist

Attachment: Weekly Progress Report cc: Lazarus Texas Refinery I, LLC

# WEEKLY PROGRESS REPORT - Falcon Refinery Federal Superfund Site, Ingleside, TX;

### 1. TASKS NECESSARY TO COMPLETE THE REMOVAL ACTION

TASK	START	EST. COMP DATE
Butane Tank – This tank contains less than one gallon of sludge. The tank will be cleaned; the sludge will be disposed of appropriately, and the tank will be inspected.	1/18/12	6/15/12
Tank 12 – The damaged roof will be removed, oil/sludge will be removed and disposed, tank will be cleaned and inspected (API 653),	4/30/12	6/11/12
Tank 7 – The damaged roof will be removed, oil/sludge will be removed and disposed, tank will be cleaned and inspected (API 653)	2/16/12	7/15/12
Tank 30 – The damaged roof will be removed, oil/sludge will be removed and disposed, tank will be cleaned and inspected (API 653)	5/14/12	5/23/12
Tank 26 – Because of the poor integrity of this tank, all liquids will be transferred to Tank 12, or frac tanks for treatment of water via water treatment system and land applied in accordance with land disposal wastewater treatment criteria and additional criteria established by the TCEQ. Sludge in this tank will be removed and disposed, tank will be cleaned and inspected (API 653), contaminated soils below tank will be removed and disposed, and tank will be demolished.	7/15/12	9/30/12
	Why was the following removed? contaminated soils below tank will be removed and disposed, tank will be repaired or demolished.	
Water Treatment System – A water treatment system capable of treating contaminated water to meet the land disposal restrictions and the criteria set up by TCEQ will be constructed with the appropriate irrigation field as approved by TCEQ. According to TCEQ, irrigation is only allowed from April 1 – August 30 (the growing season).	4/16/12  Will all windisposed irrigation disposal date?	of by or
OJECT ACTIVITIES COMPLETED THIS REPORTING PERIOD (N	//AY 14 – 18, 2	012)

2. PROJECT ACTIVITIES COMPLETED THIS REPORTING PERIOD (MAY 14 – 18, 2012)

The following activities were completed this week:

What is roof sludge?

- Removed and cleaned approximately 50% of the roof sludge in Tank 30.
- Inspected Tank 12 and (s) evaluated several options to address Tank 12 repairs.

Falcon Refinery/Access Agreements/Falcon Access Copyright 2012 TRC Solutions All Rights Reserved What are the tank 12 repairs, if tank bottom has issue, soil below must be evaluated (visually) and removed prior to repairing and putting back in service.

Continued removing debris in areas surrounding pipe racks

Patched a leaking pipe discovered at the pipe rack.

Sheared the external floating roof from Tank 30

Cleaned the external floating roof from Tank 30.

It is my understanding that a asbestos inspection was conducted and abestos removed from the refinery. Please ask Halasz. Another asbestos inspection should be done and this should be addressed on the schedule.

Received positive laboratory test results for asbestos in debris north of Process Area #1.

## 3. ACTIVITIES PLANNED FOR NEXT WEEK (MAY 21 - 25, 2012)

Continue with removal of the roof from Tank 30 on Monday.

What does this mean?

Begin treating water in frac tanks with activated carbon out of frac tanks.

 Continue conducting general housekeeping activities at the site clearing brush and maintaining firewalls.

Continue evaluating discharge limits for treated wastewater and pursue agreement from U.S. EPA and TCEQ.

Continue laying down piping for the construction of the irrigation field.

• Start repair of tank 12 for receiving water from frac tanks and tank 26.

There is nothing to work out here. You have to meet the land disposal restrictions (wastewater) for all analytes along with the TCEQ requirements or tell me why it is not appropriate.

### 4. ACTIVITIES PLANNED FOR WEEK FOLLOWING (MAY 29 – JUNE 1, 2012)

• Remove sludge and clean Tank 30 after completing roof removal activities.

- Continue gathering sludge from Tanks 30, 26, 7 and two frac tanks for centrifuging.
- Continue repairs to the bottom of Tank 12.

### **5. ISSUES ENCOUNTERED**

- Resolved the tight oil/water emulsion issue and has improved the clarity of the water from Tank 26.
- Sampled insulation in several areas north of Process Area #1 of the Falcon Refinery and identified
  asbestos in one area. The area has been restricted, material has been contained, and the debris that
  contains asbestos will be sent to an approved facility by a licensed asbestos abatement contractor.